Release Notes: Legends 4K™ Firmware 6.0.22 for Legends Pinball 4KP (July 31, 2024)

Firmware Live Date: July 31, 2024

Highlights

A new System Update v6.0.22 for all Legends Pinball 4KP devices is now available! This update includes general stability and performance enhancements and performs a one-time initialization for Advanced Features.

The system update will automatically appear for download when you power on your internet connected Legends 4K™ device.

For more information regarding Advanced Features, the Frequently Asked Questions (FAQ) can be found here.

Bug Fixes

- In AppStoreX™, "Purchase Additional Licenses" has been relocated and is no longer the default button.
- After playing a game from a FlashDriveX™ thumb drive, the FlashDriveX™ thumb drive can no longer be dismounted.

Update Notes

After the firmware has been updated, the device will display a notification stating "Advanced Features for this device have not been enabled. You can enable the Advanced Features using On-Device Purchase…". This is normal as the device has to retrieve its Advanced Features setting from the server and store it on the device. This is a one-time process.

Miscellaneous

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), Twitter (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found here.
- The latest release notes can be found here.

Known Issues Being Worked On

1. Improvements for flipper lag in Zen pinball tables are still in progress.
2. Accelerometer can not be adjusted or disabled.
3. The plunger sensitivity has a small dead zone and minimal lag affecting visual feedback. A fix is being worked on for future builds.
4. On rare occasions, CE-4K may crash to a black screen with a "Critical Error" pop-up. If this happens, you should restart your ALP 4KP device.
5. Wireless Pairing does not scan automatically on some rare occasions. In this case, the Bluetooth devices will not be listed. Restart your ALP 4KP device to fix this problem.
6. On rare occasions when you try to connect to a Wi-Fi network, CE-4K may crash.
7. Bluetooth headsets are currently not fully supported. While they will pair in the Wireless Pairing screen, audio will not be sent to them.
8. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function within Zen pinball tables.

The release notes are for reference only and subject to changes. © AtGames 2024