AT@GAMES

Release Notes: Legends 4K™ Firmware 6.0.28 for Legends Pinball 4KP (September 12, 2024)

Firmware Live Date: September 12, 2024

Highlights

A new System Update v6.0.28 for all Legends Pinball 4KP devices is now available! In addition to general stability and performance enhancements, this update includes the following new features:

- ✓ **Improved Input Latency for Zen Studios Titles**: Enhanced support now offers reduced latency for Zen Studios titles, providing a smoother gaming experience. Zen Studios improved input latency will be performed in waves, please see here for details.
- ✓ **Improved Audio Latency for Zen Studios Titles:** Enhanced support now offers improved audio latency for Zen Studios titles, providing a more responsive audio gaming experience. Zen Studios improved audio latency will be performed in waves.
- ✓ **Flash Drive X (FDX) Support**: Zen titles updated today and in the coming weeks can now be saved and played directly from Flash Drive X (FDX). Titles that have not yet been updated with the improved latency must still be run from internal memory.
- ✓ **Optimized Application Performance**: Application priority has been increased upon launch, ensuring optimal performance for a seamless gaming experience.
- ✓ **Promotional Navigation Improvement:** After receiving a message regarding a discount, selecting the "GO TO APPSTOREX" option AppStoreX™ will be refreshed with the updated discounts and AppStoreX™ will be launched.

The system update will automatically appear for download when you power on your internet connected Legends 4K™ device.

For more information regarding Advanced Features, the Frequently Asked Questions (FAQ) can be found here.

Bug Fixes

- Parental Controls manage block lists: table names have been fixed to allow viewing the entire table names.
- Boxart Discounted Price positioning adjusted for proper viewing of discount pricing.

Miscellaneous

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), Twitter (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found here.
- The latest release notes can be found here.

Release Notes: Legends 4K™ Firmware 6.0.28 for Legends Pinball 4KP (September 12, 2024)

Known Issues Being Worked On

1. Micro-Stuttering Interference From Not-Yet-Updated Tables: If you launch a Zen title that **HAS NOT** been updated with the latest latency improvements, exit it, and then launch a Zen title that **HAS** been updated with the latest latency improvements, you will experience micro-stuttering while playing the updated table. Restarting the machine will resolve this issue. This problem is temporary and will no longer occur once all Zen titles have been updated with the latency improvements.
2. On rare occasions, when the user opens Time Settings, there may be brief input delay.
3. When the Haptic Feedback is set to "Disable", Haptic Feedback and Solenoids will not be available in updated Zen tables. Changing this setting to "Enable" will allow the use of these features. This will be corrected in an upcoming release.
4. Ongoing Flipper Latency Improvements: Work to reduce flipper latency Zen pinball packs is still in progress. Updates will be rolled out during the [release schedule](#), until all packs have been addressed.
5. Accelerometer can not be adjusted or disabled.
6. The plunger sensitivity has a small dead zone and minimal lag affecting visual feedback. A fix is being worked on for future builds.
7. On rare occasions, CE-4K may crash to a black screen with a "Critical Error" pop-up. If this happens, you should restart your Legends Pinball 4KP device.
8. Wireless Pairing does not scan automatically on some rare occasions. In this case, the Bluetooth devices will not be listed. Restart your Legends Pinball 4KP device to fix this problem.
9. On rare occasions when you try to connect to a Wi-Fi network, CE-4K may crash.
10. Bluetooth headsets are currently not fully supported. While they will pair in the Wireless Pairing screen, audio will not be sent to them.
11. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function within Zen pinball tables.