Release Notes: Legends 4K™ Firmware 6.0.24 for Legends Pinball 4KP (August 23, 2024)

Firmware Live Date: August 23, 2024

Highlights

A new System Update v6.0.24 for all Legends Pinball 4KP devices is now available! In addition to general stability and performance enhancements, this update includes the following new features:

- Ability for On-Device-Purchase (ODP) discounting of AppStoreX™ (ASX) pinball packs and subscriptions.
- Ability for Premium Starter machines to purchase/enable Advanced Features
    - Until December 31, 2024, take advantage of the Buy One Get One Free promotion. Purchase one Advanced Feature (OTG or External Applications via General Loader) and receive the other free of charge.

The system update will automatically appear for download when you power on your internet connected Legends 4K™ device.
For more information regarding Advanced Features, the Frequently Asked Questions (FAQ) can be found here.

Bug Fixes

- The Series filter in PinballNet™ now sorts properly.Zaccaria Legends 4K™ Pinball Packs 10, 11, and 12 now come after Zaccaria Legends 4K™ Pinball Pack 9 instead of before Zaccaria Legends 4K™ Pinball Pack 1.
- Eliminated the false-positive message stating that Advanced Features are not enabled on a machine that already has them enabled.

Miscellaneous

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X/Twitter (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found here.
- The latest release notes can be found here.

Known Issues Being Worked On

1. Improvements for flipper lag in Zen pinball tables are still in progress.
2. Accelerometer can not be adjusted or disabled.
3. The plunger sensitivity has a small dead zone and minimal lag affecting visual feedback. A fix is being worked on for future builds.
4. On rare occasions, CE-4K may crash to a black screen with a “Critical Error” pop-up. If this happens, you should restart your ALP 4KP device.
5. Wireless Pairing does not scan automatically on some rare occasions. In this case, the Bluetooth devices will not be listed. Restart your ALP 4KP device to fix this problem.
6. On rare occasions when you try to connect to a Wi-Fi network, CE-4K may crash.
7. Bluetooth headsets are currently not fully supported. While they will pair in the Wireless Pairing screen, audio will not be sent to them.
8. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function within Zen pinball tables.

The release notes are for reference only and subject to changes. © AtGames 2024