

## Release Notes: Garfield Pinball Legends Single Pack for Legends 4K™ Pinball Machines Update (October 3, 2024)

### Garfield Pinball Legends Single Pack Version 1.7

The re-release of Garfield comes with the following improvements and enhancements.

- **Improved Input Latency:** Enhanced support now offers reduced latency, providing a smoother gaming experience.
  - Input latency has been reduced from 131.30ms down to 74.07ms.
- **Improved Audio Latency:** Enhanced support now offers improved audio latency, providing a more responsive audio gaming experience.
- **Flash Drive X (FDX) Support:** Garfield can now be saved and played directly from Flash Drive X (FDX).
- **Improved Tournament Participation:** You no longer have to beat your local Top 5 scores to participate in Tournaments.
- **Volume Improvements:** Improved voiceover levers and normalized the volume of the sound channels within the table to be about the same as non-Zen tables.

Current owners of Garfield Pinball Legends Single Pack can update their table via AppStoreX™ by following these steps:

- Go to AppStoreX™
- Select Garfield Pinball Legends Single Pack
- Choose Update

And if you haven't already purchased the Garfield Pinball Legends Single Pack, it is available on the [AtGames E-Store](#) and via Legends On-Device-Purchase (ODP) at AppStoreX™ today.

### Miscellaneous:

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found [here](#).
- The latest release notes can be found [here](#).

The Garfield Pinball Legends Single Pack is playable on all currently released Legends 4K™ machines and will be compatible with future AtGames Legends 4K™ devices.

### Known Issues Being Worked On:

1. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function properly within Zen pinball tables.
2. When the Haptic Feedback is set to "Disable", Haptic Feedback and Solenoids will not be available in Garfield. Changing this setting to "Enable" will allow the use these features. This will be corrected in an upcoming firmware release.
3. As stated in Known Issue #1 in the Firmware v6.0.28 Release Notes, found [here](#), after playing a not-yet-updated Zen table, updated Zen tables will experience micro-stuttering. Restarting the machine will resolve this issue.

