

# Release Notes: Gearbox® Pinball Legends Mini Pack for Legends 4K™ Pinball Machines Update (October 3, 2024)

## Gearbox® Pinball Legends Mini Pack Version 1.16

The re-release of the Gearbox® Pinball tables comes with the following improvements and enhancements.

- **Improved Input Latency:** Enhanced support now offers reduced latency, providing a smoother gaming experience.
  - Borderlands®: Vault Hunter Pinball from 121.63ms down to 70.90ms.
  - Brothers in Arms®: Win the War Pinball from 127.03ms down to 69.40ms.
  - Homeworld®: Journey to Hiigara Pinball from 128.53ms down to 75.80ms.
- **Improved Audio Latency:** Enhanced support now offers improved audio latency, providing a more responsive audio gaming experience.
- **Flash Drive X (FDX) Support:** Gearbox® Pinball tables can now be saved and played directly from Flash Drive X (FDX).
- **Improved Tournament Participation:** You no longer have to beat your local Top 5 scores to participate in Tournaments.
- **Volume Improvements:** Normalized the volume of the sound channels within the table to be about the same as non-Zen tables.

Current owners of Gearbox® Pinball Legends Mini Pack can update their table via AppStoreX™ by following these steps:

- Go to AppStoreX™
- Select Gearbox® Pinball Legends Mini Pack
- Choose Update

And if you haven't already purchased the Gearbox® Pinball Legends Mini Pack, it is available on the [AtGames E-Store](#) and via Legends On-Device-Purchase (ODP) at AppStoreX™ today.

### Miscellaneous:

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found [here](#).
- The latest release notes can be found [here](#).

Gearbox® Pinball Legends Mini Pack tables are playable on all currently released Legends 4K™ machines and will be compatible with future AtGames Legends 4K™ devices.

### Known Issues Being Worked On:

1. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function properly within Zen pinball tables.
2. Due to the size of the Gearbox® Pinball tables, users will see a short pause when launching them. It occurs just before their playfields appear.
3. When the Haptic Feedback is set to "Disable", Haptic Feedback and Solenoids will not be available in Gearbox® Pinball tables. Changing this setting to "Enable" will allow the use these features. This will be corrected in an upcoming firmware release.
4. As stated in Known Issue #1 in the Firmware v6.0.28 Release Notes, found [here](#), after playing a not-yet-updated Zen table, updated Zen tables will experience micro-stuttering. Restarting the machine will resolve this issue.