

Release Notes: Legends 4K™ Firmware 6.0.32 for Legends Pinball 4KP (January 15, 2025)

Firmware Live Date: January 15, 2025

Highlights

A new System Update v6.0.32 for all Legends Pinball 4KP devices is now available! In addition to general stability and performance enhancements, this update includes the following new features:

- New Offline Mode
 - Automatically assigns the license for an AppStoreX™ pack to a device after launching one of its tables/games
 - Soft Launch of Enhanced License Management between multiple devices (full functionality will be in the next firmware release)
- Enhanced BYOG (Bring your Own Games) experience via Retroplayer's improved Arcade Control Panel (ACP) support
 - Retroplayer is the platform that runs built-in arcade/console games and BYOG UCES
 - The improved Retroplayer will be delivered as a component update alongside this firmware.

Note: Any packs that had been manually taken offline prior to updating to this firmware may no longer be registered as offline on that device. If you wish to utilize the manual offline mode again, you will need to reselect your packs.

These system updates will automatically appear for download when you power on your internet connected Legends 4K™ device.

Miscellaneous

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found [here](#).

Known Issues

1. Accelerometer can not be adjusted or disabled.
2. The plunger sensitivity has a small dead zone and minimal lag affecting visual feedback. A fix is being worked on for future builds.
3. On rare occasions, CE-4K may crash to a black screen with a "Critical Error" pop-up. If this happens, you should restart your Legends Pinball 4KP device.
4. Wireless Pairing does not scan automatically on some rare occasions. In this case, the Bluetooth devices will not be listed. Restart your Legends Pinball 4KP device to fix this problem.
5. On rare occasions when you try to connect to a Wi-Fi or Ethernet network, CE-4K may crash.
6. Bluetooth headsets are currently not fully supported. While they will pair in the Wireless Pairing screen, audio will not be sent to them.
7. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function within Zen pinball tables.
8. While flipping through multiple tables, or pages of tables, users may experience a very slight slowdown during some transition animations.
9. Owners of more than 1 Legends 4K™ Pinball Machine may see a "Game Launch Failed" message. This is one of the Enhanced Offline Mode features that will be corrected in the next firmware.
10. In some cases, while a device is offline, Zen tables scores may not save to the local leaderboard. They will reappear when the device is restarted.
11. Some BYOG games may not support save files.
12. After a device is idle for an extended period, some Arcade Control Panels (ACP) may exhibit a brief 1-3 second hesitation before responding.
13. After updating firmware, some users may experience loss of audio or static in their speakers. This can usually be remedied by a reboot. If audio issues persist, power down the machine, detach the power cable for 10 seconds, reconnect the power cable, and then turn the machine back on.