

Release Notes: Williams™ Pinball: Universal Monsters Legends Mini Pack for Legends 4K™ Pinball Machines (October 2, 2024)

Williams™ Pinball: Universal Monsters Legends Mini Pack Version 1.8



Two scarily authentic Williams™ and Bally™ pinball tables—and a whole party of iconic Universal Monsters await you in Williams™ Pinball: Universal Monsters Legends Mini Pack, available on the AtGames E-Store and via Legends On-Device-Purchase (ODP) at AppStoreX™ today.

Universal Classics Pinball™ Legends Mini Pack Includes These Tables:

- Williams™ Pinball: Monster Bash™
- Williams™ Pinball: The Creature From The Black Lagoon™

Technical Statistics:

- Williams™ Pinball: Monster Bash™ has an average flipper latency of 79.93ms and a display resolution of 2560x1440 pixels.
- Williams™ Pinball: The Creature From The Black Lagoon™ has an average flipper latency of 74.37ms and a display resolution of 2240x1260 pixels.

Williams™ Pinball: Universal Monsters Legends Mini Pack is playable on all currently released Legends 4K™ machines and will be compatible with future AtGames Legends 4K™ devices.

Miscellaneous:

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found [here](#).
- The latest release notes can be found [here](#).

Known Issues Being Worked On:

1. In Tiled Mode, the table name for Williams™ Pinball: The Creature From The Black Lagoon™ overlaps the box art and the bottom half of the letter G in Lagoon is cut off. This will be corrected in a future update.
2. In some situations, players may experience minor ball stuttering during gameplay.
3. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function properly within Zen pinball tables.
4. When the Haptic Feedback is set to "Disable", Haptic Feedback and Solenoids will not be available in Williams™ Pinball: Universal Monsters tables. Changing this setting to "Enable" will allow the use these features. This will be corrected in an upcoming firmware release.
5. As stated in Known Issue #1 in the Firmware v6.0.28 Release Notes, found [here](#), after playing a not-yet-updated Zen table, updated Zen tables will experience micro-stuttering. Restarting the machine will resolve this issue.