

Release Notes: **Legends 4K™ Firmware 6.0.29** **for Legends Pinball 4KP (October 16, 2024)**

Firmware Live Date: October 16, 2024

Highlights

A new System Update v6.0.29 for all Legends Pinball 4KP devices is now available! In addition to general stability and performance enhancements, this update includes the following new features:

- Soft Launch of AtGames Mature Audience™ (AMA™) Automated Content Filtering
 - Option to auto-block AMA™ Content for subaccounts
 - Alternate AppStoreX™ Box Art for AMA™ Content
- Local High Scores on Backglass
 - Users can now choose to see a Local Leaderboard scores on the Backglass instead of the Global/Online Leaderboards.

AMA™ Usage Note: Automatic blocking of AMA™ Content for subaccounts created in Parental Controls will begin automatically blocking content downloaded after the subaccount is created. Any previously installed AMA™ content will need to be manually added to the subaccount's block list.

The system update will automatically appear for download when you power on your internet connected Legends 4K™ device.

Bug Fixes

- Dynamic font scaling for extra long table/game names
- Haptic/Solenoid settings now work for all Zen tables
- Text/dialog corrections in the Wi-Fi and Notifications screens

Miscellaneous

- For the latest information on future releases, please follow AtGames on Facebook (@AtGamesGaming), X (@AtGamesGaming), or Instagram (@atgamesgaming).
- Legends 4K™ Pinball Packs can be found [here](#).

Known Issues Being Worked On

1. Accelerometer can not be adjusted or disabled.
2. The plunger sensitivity has a small dead zone and minimal lag affecting visual feedback. A fix is being worked on for future builds.
3. On rare occasions, CE-4K may crash to a black screen with a "Critical Error" pop-up. If this happens, you should restart your Legends Pinball 4KP device.
4. Wireless Pairing does not scan automatically on some rare occasions. In this case, the Bluetooth devices will not be listed. Restart your Legends Pinball 4KP device to fix this problem.
5. On rare occasions when you try to connect to a Wi-Fi network, CE-4K may crash.
6. Bluetooth headsets are currently not fully supported. While they will pair in the Wireless Pairing screen, audio will not be sent to them.
7. Switching the Flipper and Nudge buttons inside of the Pinball Settings does not function within Zen pinball tables.